Felt and tissue for installation on walls and ceilings. Provides an aesthetic look with or without pattern depending on design chosen. Enhances the surface and prevents cracking. Finish treatment with paint in desired gloss and colour.

Product properties

Precoated quality glass tissue with coarse structure for installation on walls and ceilings. Easy installation. Saturated surface that normally does not require priming paint.

- Precoated
- Uniform surface
- Prevents cracking

Product use

Living rooms, hallways and entrance areas, offices, kitchens, toilets, commercial premises, clinics and shops. Not suitable for surfaces requiring wet room water- and damp-proofing. Concrete, light concrete, plaster, plasterboard and gypsum fibre board.

Substrate

Must be clean, dry, firm and suitable for surface treatment.

Treatment

Remove loose material and paint by cleaning and sanding. Remove existing wallpaper. Remove dirt, grime, grease and chalking materials by cleaning. Water-soluble discolouration, nicotine and soot are cleaned and treated with blocking primer. Hard, smooth substrates should be sanded to a matt finish and painted with primer. Smooth out cracks, unevenness and holes with filler. Paint absorbent and porous substrates with primer.

Application

The glass tissue panels are cut into full lengths corresponding to the surface to be covered, + 10 cm for trimming. Apply glue evenly to the contact surface, 1-2 panels at a time. Hang the panels edge to edge, taking into account any pattern adjustment. Remove air bubbles using a wallpaper spatula. Cut away the excess glass felt against adjacent surfaces. Wipe off excess adhesive with a sponge and lukewarm water. Always test adhesion and result before hanging

Expected result

Uniform, even and saturated surface which normally does not require priming paint. The surface may have some unevenness. Finish treat with paint in desired gloss and colour. Best results reached after two coats. Avoid placing loads on the surface before the treatment is fully cured.

Useful Information

Ensure good ventilation during and after hanging.

Good practice

1 x 25 m structure 208 Precoated glass tissue 130 g/m² Recommended adhesive: Flügger Adhesive 378 Strong

Supplementary Info

Remove as much adhesive as possible from brushes before cleaning. Do not pour residue/remains of paint down the drain; take it to your local recycling centre. Minimise your paint waste by calculating how much paint you need in advance. Store leftover paint properly so the remains can be reused, which minimises the environmental impact.

Technical Data

Cleaning of tools etc.	Water
Storage	Store dry and clean
Working temperature	Min. +10°C

Current TDS Version

February 2023